25X1 0-18-200524-8 Copy 8 of 9 copies

13 March 1968

This document contains

__3__pages.

EVALUATION SUMMARY

Mission <u>BX-6856</u>

1. Processing and Titling - Good/Fair (Field)

2. Physical Condition - Good

3. Hypo Retention Negligible

4. Exposure (based on density) - Medium

5. General Comments:

- A. Mission contained 18 parts.
- B. Dye retention prevalent. Reprocessing required to remove excess dye.
- C. A total of 7 parts with approximately 15 frames in each required retitling.
- D. Ultrasonic splice--part 15, frame 1102--was not taped at presplice.
- E. A few bulls-eye targets were not coated with lacquer.
- F. Part 13 was dual printed (.00/.50).
- G. First time grid instructions idents and bulls eye targets were used in the field.
- H. Small amounts of kinks and embedded dirt were noted intermittently throughout.
- I. Avg. base fog was .30 before dye removal.

MISSION NO. BX-6856EVALUATION REPORT

| Evaluated | By | Q.C. | Camera | Fwd/Aft |
|------------|------|---------------|-----------|---------|
| Evaluation | Date | 12 March 1968 | Emulsion_ | 3404 |

Film Metering Normal

Film Tracking Fair to good

Clock Operation Exposure Good

Counter Operation Operational

Data Chamber (image quality) Good

Apparent Resolution Normal

Apparent Granularity Normal

Density Medium

Contrast Medium

Discrepancies:

| Part | <u>Frames</u> | Comments |
|------|-------------------------|---|
| ı | 1-76 | Intermittent abrasions, emulsion scratches |
| 2 | 77-152 | Intermittent abrasions, emulsion scratches |
| 3 | 153-228 | Intermittent abrasions, emulsion scratches |
| 4 | 229-304 | Intermittent abrasions, emulsion scratches |
| 5 | 373 | HT-2 test spot |
| . 6 | 381-456 | Emulsion scratch |
| 7 | | |
| 8 | 533-608 | Intermittent emulsion scratch |
| 9 | 609-684 | Intermittent emulsion scratch, minus density streak Aft camera only |
| 10 | 693 | HT-2 test spot |
| 11 | 762 | Emulsion pickoff |
| 12 | 837 - 912 885 | Minus density streak on Aft frames only Emulsion dig |

| Discrepancies (Cont'd) | Camera |
|------------------------|--------|
|------------------------|--------|

| Part | Frames | Comments |
|------|----------------------------------|--|
| 13 | 913-988 914 987 927-930 | Intermittent emulsion scratch Handling marks Cinch marks Splice |
| 14 | 989-1064 1055 | Intermittent emulsion scratch Abrasions |
| 15 | 1065 - 1140 1102 | Intermittent emulsion scratch Ultrasonic splice |
| 16 | 1141 - 1216 1162 | Intermittent emulsion scratch Base scratch |
| 17 | 1217-1292 | Intermittent emulsion scratch |
| 18 | 1293-1310 1308 | Intermittent emulsion scratch HT-2 test spot |